

# Laporan Normalisasi Sungai dan Drainase Satgas DPUPRPKP

Tanggal : 30 Maret 2023

Lokasi	Uraian
Jl. Jupri, Kelurahan Pisang Candi, Kecamatan Sukun	Normalisasi saluran yang sering meluap saat debit hujan tinggi serta pengerukan sedimen secara manual di bawah jembatan.



0 %



0 %



0 %



0 %



50 %



50 %





50 %



50 %



50 %



50 %



50 %



50 %





50 %



50 %



50 %



100 %



100 %



100 %

K O T A M A L A N G



100 %



100 %



100 %



100 %

DPUPRPKP  
K O T A M A L A N G