

# Laporan Normalisasi Sungai dan Drainase Satgas DPUPRKP

## Tanggal : 2 Mei 2023

Lokasi	Uraian
Jl. Brigjen Katamso (dari perempatan trafficlight ke arah barat)	Normalisasi 4 titik sumbat saluran dari sedimentasi, pipa2 PDAM yang melintang, batang kayu, serta akar pohon.



0 %



0 %



0 %



0 %



50 %



50 %



50 %



50 %



50 %



50 %



100 %



100 %

K O T A M A L A N G



0%



0%



50%



50%



50%



50%

K O T A M A L A N G



50 %



50 %



50 %



50 %



100 %



100 %

K O T A M A L A N G



50 %



50 %



100 %



100 %

DPUPRRPKP  
K O T A M A L A N G